




6B - (6 PIN BAYONET)





LEAD	COLOR	6 PIN
SIGNAL+	RED	A
SIGNAL-	BLACK	B
EXCITATION+	WHITE	C
EXCITATION-	GREEN	D
CALIBRATION	BLUE	E
CALIBRATION	ORANGE	F

6S - (6 PIN THREADED)



LEAD	COLOR	6 PIN
EXCITATION+	WHITE	1
EXCITATION-	GREEN	2
SIGNAL-	BLACK	3
SIGNAL+	RED	4
NOT USED		5
NOT USED		6

8S - (8 PIN THREADED)



LEAD	COLOR	8 PIN
EXCITATION+	WHITE	A
SIGNAL+	RED	B
EXCITATION-	GREEN	C
SIGNAL-	BLACK	D
CALIBRATION	BLUE	E
CALIBRATION	ORANGE	F
NOT USED		G
NOT USED		H

WIRING : MELT PRESSURE TRANSMITTERS (6B - 6 PIN)

4-20mA

PIN	4-20mA (2wire)	4-20mA (4wire)
A (red)	SIGNAL (+)	SIGNAL (+)
B (black)	SIGNAL (-)	SIGNAL (-)
C (white)	n/a	EXCIT. (+)
D (green)	n/a	EXCIT. (-)
E (blue)	CAL 1	CAL 1
F (orange)	CAL 2	CAL 2

VOLTAGE

PIN	VOLTAGE(4wire)
A (red)	SIGNAL (+)
B (black)	SIGNAL (-)
C (white)	EXCIT. (+)
D (green)	EXCIT. (-)
E (blue)	CAL 1
F (orange)	CAL 2

Standard 4-20mA DC, 2 wire Transmitter Wiring

